

<b>L Number</b>	<b>Hits</b>	<b>Search Text</b>	<b>DB</b>	<b>Time stamp</b>
<b>1</b>	<b>3</b>	<b>"air conditioning" and "preheat exchange"</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT</b>	<b>2004/07/25 13:11</b>
<b>2</b>	<b>67</b>	<b>"air conditioning" and "pre-heater"</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT</b>	<b>2004/07/25 13:00</b>
<b>3</b>	<b>2</b>	<b>("air conditioning" and "pre-heater") and "indoor unit"</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT</b>	<b>2004/07/25 13:00</b>
<b>4</b>	<b>11</b>	<b>("3611743"   "4100763"   "4480533"   "4733543"   "4854376"   "4974915"   "5293758"   "5308156"   "5404939"   "5687581"   "5979169").PN.</b>	<b>USPAT</b>	<b>2004/07/25 13:02</b>
<b>5</b>	<b>2566</b>	<b>"air conditioning" and "indoor unit"</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT</b>	<b>2004/07/25 13:04</b>
<b>6</b>	<b>1315</b>	<b>("air conditioning" and "indoor unit") and "outdoor unit"</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT</b>	<b>2004/07/25 13:04</b>
<b>7</b>	<b>7</b>	<b>((("air conditioning" and "indoor unit") and "outdoor unit") and "preheat"</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT</b>	<b>2004/07/25 13:04</b>
<b>8</b>	<b>256</b>	<b>"air conditioning" and "preheater"</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT</b>	<b>2004/07/25 13:18</b>
<b>9</b>	<b>4</b>	<b>("air conditioning" and "preheater") and "indoor unit"</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT</b>	<b>2004/07/25 13:26</b>
<b>10</b>	<b>4</b>	<b>("3520147"   "3831663"   "4189929"   "4720982").PN.</b>	<b>USPAT</b>	<b>2004/07/25 13:16</b>
<b>11</b>	<b>13</b>	<b>("1874803"   "2690649"   "2881011"   "2934915"   "3188829"   "3230732"   "3301002"   "3308877"   "3850006"   "3916638"   "3984050"   "4069686"   "4103510").PN.</b>	<b>USPAT</b>	<b>2004/07/25 13:16</b>
<b>12</b>	<b>8762</b>	<b>"air conditioning" and "outdoor"</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT</b>	<b>2004/07/25 13:18</b>
<b>13</b>	<b>374</b>	<b>62/\$.ccls. and "preheat"</b>	<b>USPAT; US-PGPUB; EPO; JPO; DERWENT</b>	<b>2004/07/25 13:27</b>

14	7	(62/\$.ccls. and "preheat") and "indoor unit"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/07/25 13:26
15	13	62/\$.ccls. and "preheat exchanger"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/07/25 13:32
16	9	("2203477"   "3103154"   "3269801"   "3313123"   "3329077"   "3651659"   "3827218"   "3883637"   "3908900").PN.	USPAT	2004/07/25 13:30
18	0	(62/\$.ccls. and "ceiling mounted") and "preheat"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/07/25 13:32
17	54	62/\$.ccls. and "ceiling mounted"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/07/25 14:22
19	9	("4607497"   "4888959"   "4898003"   "4926655"   "4958504"   "5579649"   "5588305"   "5860288"   "6105383").PN.	USPAT	2004/07/25 13:42
20	5	("2638757"   "2920460"   "4507940"   "4560395"   "4786300").PN.	USPAT	2004/07/25 13:55
21	4	("4898003"   "4958504"   "5211219"   "5417279").PN.	USPAT	2004/07/25 14:17
22	6	("2973703"   "3263438"   "3929285"   "4076073"   "4090434"   "5495724").PN.	USPAT	2004/07/25 14:17
23	224	62/\$.ccls. and "preheater"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/07/25 14:26
24	10	(62/\$.ccls. and "preheater") and "external air"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/07/25 14:57
25	30	("1888242"   "1965078"   "2048137"   "2214057"   "2237332"   "2254185"   "2391838"   "2495856"   "2522484"   "2793812"   "2917288"   "2984459"   "3415313"   "3587243"   "3656542"   "3791369"   "3835921"   "4099553"   "4109704"   "4428205"   "4512397"   "4549601"   "4607498"   "4750545"   "4761966"   "5060720"   "5179998"   "5181552"   "5303771"   "5337577").PN.	USPAT	2004/07/25 14:29
26	2	("5595068").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/07/25 15:01